Item: 7

DC/23/3115/FUL


Part demolition, refurbishment and extension of an existing single family home.

Seacroft, Millfield Road, Walberswick



North Planning Committee - 09 January 2023

Site Location Plan



Aerial Photograph



Insert Google Streetview Link




















































Existing block plan




Proposed block plan




Demolition Plan





Existing elevations





Existing elevations





Proposed elevations



3D Visualisations





Proposed materials

Key:


a) Zinc Roof

b) Rich Timber


c) Dark Brick

d) Purbeck Stone


e) Dark Aluminium Windows and doors




Existing Ground Floor Plan




Existing First Floor Plan




Proposed Ground Floor Plan




Proposed First Floor Plan



Proposed Concept Plan



Landscaping details



Light spill measures

There is no new garden lighting as part of this application.

Any external building lighting to be non-intrusive, low-level, downward facing, and will turn off when not in use. Specification to be in-line with recommendations;

har IL

-31

- Not more than 500 lumens
- Less than or equal to 3000k colour

To the rear elevation (looking south towards the coastal path) roof lights have been avoided, and all proposed fenestration to the extension is recessed at first floor with an adjacent solid catslide roof.

Windows will be deep recessed in external wall with large over hanging eaves to mitigate light spill. 6

Clerestory lights have been positioned away from AONB and will have lower LTV (Light Transmission Value) per the recommended guidance

Large eaves over hangs limiting light spill.

Curtains & Blinds on windows

Low level downward facing external lighting on balcony

Internal lights installed away from perimeter glazing & Secondary lighting in the form of low-lux lamps

Ground floor openings set back under balcony reducing light spill

STATES AND A STATE AND AND A DESCRIPTION OF THE ADDRESS OF THE ADD

Visual Impact



Visual Impact



Material Planning Considerations and Key Issues

- Design and Conservation
- Amenity
- Biodiversity
- Highway Safety

Recommendation

Recommended for approval subject to conditions as outlined within the report – summarised below:

(As per Pages 56-58 of the report)

- Time limit
- Plans
- Materials
- Development in accordance with ecology appraisal
- No foliage removal in bird nesting season
- Lighting design strategy for biodiversity
- New glazing to Visible Light Transmittance (VLT) of 0.65 or lower.
- No first floor above snug
- Tree Protection