

							ELECTR	ICAL TESTI	NG							
Number of properties requiring electrical check 4,512	% Overall EICRs compliant 10 years	Trend from previous month	% of Communal Area EICRs compliant 10 years (Included in the figures)	Trend from previous month	% of Domestic EICRs compliant 10 Years	Trend from previous month	% of EICRs compliant within 5 years	Trend from previous month	% of EICRs compliant between 5 and 10 years	Trend from previous month	% of EICRs Non- compliant Over 10 Years	Trend from previous month	Number of EICRs completed in a month	Trend from previous month	10% of third party quality assurance checks on EICR's	Trend from previous month
arget Actual Performance	4,512 4,407 97.67%		87 83 95.40%		4,512 4,407 97.67%	1	4,512 4,026 89.23%	1	0 381 8.44%	↓	0 63 1.40%	↓	109 73 66.97%	₽	11 0 0.00%	
Comment:	•						onger needing a		•	•	been completed l	out no SOR	codes so the sch	eme has no	ot picked thes	e up. There
							WATI	ER HYGIEN	E							
Number of properties requiring water checks:	Properties with communal water facilities this	Trend from	Number of water risk assessments overdue for	Trend from	Number of WRAs where it was not renewed	Trend from	Number of remedial actions	Trend from	Number of Priority 0 (Immediate) remedial	Trend from	Number of Priority 1 (Short term - 2 months)	Trend from	Number of Priority 2 (Medium term - 9 months)	Trend from	Number of Priority 3 (Long term - 18 months)	Trend from
16	includes a 10% flat inspections	previous month	review	previous month	prior to expiry	previous month		previous month	actions	previous month	remedial actions	previous month	remedial actions	previous month	remedial actions	previous month
arget/Raised Actual Performance	16 16 100.00%	•	0 0 0.00%		0 0 0.00%		45 31 68.89%		0		1 1 100.00%		42 28 66.67%		2 2 100.00%	
Comment:	The last two re	ports have	now been rece	ived, issued t	o Nemco for p	ricing and the	rest to the inho	use DLO								
						AS	BESTOS MAN	AGEMENT	(Communal)							
Number of properties requiring Asbestos check 95	Number of communal areas surveyed for asbestos	Trend from previous month	% of Asbestos containing material reinspected	Trend from previous month	Number of properties which expired within the month	Trend from previous month	% of remedial actions completed	Trend from previous month	Asbestos Management Surveys in month	Trend from previous month	Asbestos Refurbishment Surveys in month	Trend from previous month	Bulk Samples in month	Trend from previous month	Air Testing Services in month	Trend from previous month
Farget Actual Performance	95 95 100.00%	•	139 0 0.00%		0		0		9		6		5		4	

							LIF	T SAFETY										
Number of properties requiring LOLER 82 Target Actual Performance	Number of lifts and stair lifts requiring a LOLER examination 82 82 100.00%	Trend from previous month	Number of lifts overdue a LOLER examination 0 0	Trend from previous month	Number of stair-lifts overdue a LOLER examination 0 0	Trend from previous month	Number of properties which expired within the month 0 0 0.00%	Trend from previous month	Percentage of Stair lifts with an up to date service 70 69 98.57%	Trend from previous month	Percentage of passenger lifts with an up to date service 12 7 58.33%	Trend from previous month	Number of lifts and stair lifts where a service was not completed prior to the due date 0 0.00%	Trend from previous month	Percentage of lifts out of action during the month 0 0	Trend from previous month	-	
Comment:	All Passenger Lifts are on target and we for the stair lifts we have 6 outstanding: 1x delayed - unsuitable working environment on site. 2x Delay due to Christmas. 1x booked for Monday 09/01/2023. 1x booked 13 January.																	
Number of properties requiring Actions following inspections	Number of fire remedial actions raised to date	Number of fire remedial actions allocated to date	Number of fire remedial actions not	Number of fire remedial actions completed from April 2022	Number of fire remedial actions outstanding	Out of time action (included in the outstanding figures)	Number of Water remedial actions raised to date	Number of Water remedial actions allocated to date	Number of Water remedial actions not allocated to date	Number of Water remedial actions completed	Number of Water remedial actions	Number of Water remedial actions out of time		actions	Number of LOLER remedial actions not allocated to date	Number of LOLER remedial actions completed	Number of LOLER remedial actions outstanding	Numb LOL reme action of ti
Totals	1,440	1,440	0	517	969	38	95	95	0	81	14	0	110	110	0	90	20	0
Comment:	These are the three areas that following surveys/inspections have produced more actions. Fire - Trail have complete around 200 which have not been closed down as they have not completed them on Twine and we are still waiting for P&D for there data. The Water Actions have been split between the inhouse DLO and Nemco, prices received and approved.														being			